Form 9-331 (May 1963)

UNITED STATES DEPARTMENT C THE INTERIOR (Other Instructions on verse side) OFFICIAL COLORS (SUBMET IN TRIPLICATE)

Form approved.
Rudget Bureau No. 42 R1424.
5. LEASE DESIGNATION AND SERIAL NO.

	GEOLOGICAL SURVEY		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
		7. UNIT AGREEMENT NAME	
WELL WELL OTHER		8. FARM OR LEASE NAME	
Amoco Production Company		Horton Federal	
3. ADDRESS OF OPERATOR P. O. Drawer A, Levelland, Texas 79336 4. Location of Well (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2310' FSL X 1650' FWL, Sec 30 (Unit K, NE/4 SW/4)		9. WELL NO.	
		10. FIELD AND POOL, OR WILDCAT	
		Milnesand San Andres	
		11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA	
		30-8-35 NMPM	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF,	RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
	4228' RDB		Roosevelt NM
16. Check A	Appropriate Box To Indicate No	ature of Notice, Report, or C	Other Data
NOTICE OF INT			UENT REPORT OF:
TEST WATER SHUT-OFF	PULL OB ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDON MENT*
(Other)		(Other) Percet result	s of multiple completion on Well
(Other)		Completion or Recomp	oletion Report and Log form.) s, including estimated date of starting any cal depths for all markers and zones perti
4670' - 78', 4680' -	ease production, propo 93' with 5000 gals 20	se to acidize perfor % NE Acid and 8,000	rations 4656' - 64', lbs 100 mesh sand.
In an effort to incr 4670' - 78', 4680' - Return well to produ	93' with 5000 gals 20	se to acidize perfor % NE Acid and 8,000	rations 4656' - 64', lbs 100 mesh sand.