## SUNDRY NOTICES AND REPORTS ON WELLS

SUBSEQUENT REPORT OF WATER SHUT-OFF
SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
SUBSEQUENT REPORT OF ALTERING CASING
SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
SUBSEQUENT REPORT OF ABANDONMENT
SUPPLEMENTARY WELL HISTORY

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Mark Poderal		ikotzenist Li,		, 19 <b>.63</b>
Well No	ed toti ft.	from $\begin{bmatrix} \mathbf{N} \\ \mathbf{S} \end{bmatrix}$ line a	nd 🖽 ft. fror	$n \begin{bmatrix} E \\ W \end{bmatrix}$ line of sec.
Style Style son. to	The state	ීලාන්	Boo M	•
(1/ Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)	
Wildowt	NUMBER	elt		an Herico
(Field)	(Co	ounty or Subdivision)	(	State or Territory)

The elevation of the derrick floor above sea level is 1835 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

## On Normbur 10, res 290° of must J.55, 8 min 30 12. coming \$ 5/8° chanter. Cummited with 175 sm. Circulatel to surface. Held blo lie. pressure for 16 hours. Frilled out plug on Nov.11, 1963. Pressure Meld.

## Commuting performed by Haliburtin Co.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company	Juck L. Mclieilan	
Address	Bux 848	$\sim$
	Formell, Ber Festico	By Jare J. M. Clolla
		Title Title

Budget Bureau No. 42-R358.4.