NO. OF COPIES RECEIVED		
DISTRIBUTION		Form C-103 Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103
FILE		Effective 1-1-65
U.S.G.S.	AUG 25   15 FM '67	5a. Indicate Type of Lease
		State X Fee
OPERATOR		5. State Oil & Gas Lease No.
(DO NOT USE THIS FORM FOR PRC USE "APPLICAT	AND TICES AND REPORTS ON WELLS POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ION FOR PERMIT	E-10047
OIL GAS WELL WELL	SUN OIL COULTANT	7. Unit Agreement Name
2. Name of Operator Sunray DX 011 Company	NAME CHARGENED TO SUN OIL COMPANY	8. Farm or Lease Name N. M. "AY" State
3. Address of Operator	····••.	9. Well No.
P. O. Box 1416, Roswe	11, New Mexico	4
4. Location of Well		10. Field and Pool, or Wildcat
T 2	110 FEET FROM THE South LINE AND 1980 FEET F	Todd San Andres
UNIT LETTER ,	FEET FROM THE LINE AND FEET F	ROM LUUG DEM AMULED
	DN <u>36 township 78 range</u> <u>35E</u> NM	
THE <b>East</b> LINE, SECTION	36     TOWNSHIP     78     RANGE     35E     NM       15. Elevation (Show whether DF, RT, GR, etc.)     4170 DF	PM. 12. County Roosevelt
THE <b>East</b> LINE, SECTION	DN <u>36</u> TOWNSHIP <u>78</u> RANGE <u>35E</u> NM 15. Elevation (Show whether DF, RT, GR, etc.) <u>4170 DF</u> Appropriate Box To Indicate Nature of Notice, Report or 0	PM. 12. County Roosevelt
THE <b>East</b> LINE, SECTION	Appropriate Box To Indicate Nature of Notice, Report or 0	PM. 12. County Roosevelt
THE <b>East</b> LINE, SECTION 16. Check A NOTICE OF IN PERFORM REMEDIAL WORK	36 TOWNSHIP 78 RANGE 35E NM   15. Elevation (Show whether DF, RT, GR, etc.) 4170 DF 4170 DF   Appropriate Box To Indicate Nature of Notice, Report or ONTENTION TO: SUBSEQUE   PLUG AND ABANDON REMEDIAL WORK	PM. 12. County Roosevelt Other Data INT REPORT OF: ALTERING CASING
THE <b>EAST</b> LINE, SECTION 16. Check A NOTICE OF IN PERFORM REMEDIAL WORK	Appropriate Box To Indicate Nature of Notice, Report or UNTENTION TO: PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS.	PM. 12. County Roosevelt Other Data ENT REPORT OF:
THE <b>East</b> LINE, SECTION 16. Check A NOTICE OF IN PERFORM REMEDIAL WORK	36   TOWNSHIP   78   BANGE   35E   NM     15. Elevation (Show whether DF, RT, GR, etc.)   4170 DF   4170 DF     Appropriate Box To Indicate Nature of Notice, Report or ONTENTION TO:   SUBSEQUE     PLUG AND ABANDON   REMEDIAL WORK   Indicate ORILLING OPNS.     CHANGE PLANS   CASING TEST AND CEMENT JOB   Indicate ORILLING OPNS.	PM. 12. County Roosevelt Other Data INT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT
THE <b>East</b> LINE, SECTION 16. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON	Appropriate Box To Indicate Nature of Notice, Report or UNTENTION TO: PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS.	PM. 12. County Roosevelt Other Data INT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT

- 1. Moved in and rigged up pulling unit.
- Pulled rods and tubing. 2.
- 3. Fraced down casing w/30,000 gallons ref. oil and 40,000# sand.
- Ran tubing and checked sand fill. OK. 4.
- Ran rods and put on pump. 5.
- Recovering load. 6.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNED John Kasting John Hastings		District Engineer	DATE August 23, 1967		
	n 1 € 1	· ·			
APPROVED BY		CF/	DATE		
CONDITIONS OF APPROVAL, IF ANY:		*			