NO. OF COPIES RECEIVED	
DISTRIBUTION HOSES OF TICE Q. C. C.	Form C-103 Supersedes Old
SANTA FE NEW MEXICO OIL COMSERVATION COMMISSION	C-102 and C-103
The mexico of equal in the commission	Effective 1-1-65
U.S.G.S.	5a. Indicate Type of Lease
LAND OFFICE	State 📕 Fee. 🗌
OPERATOR	5. State Oil & Gas Lease No.
SUMPRY MOTICES AND REPORTS ON WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.)	
I. OIL GAS OTHER-	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
Swaray DX Oil Company	H. M. State *AZ*
3. Address of Operator	9. Well No.
P. O. Bex 1416, Roswell, New Mexico  4. Location of Well	13
A 440 % 440	10. Field and Pool, or Wildcat  Chaveree San Andres
UNIT LETTER FEET FROM THE LINE AND FEET FR	
THE LINE, SECTION 34 TOWNSHIP 78 RANGE 338 NMF	». (((((((()(()()()()()()()()()()()()()()
15. Elevation (Show whether DF, RT, GR, etc.)	12, County
ALOA BY	Rocevelt
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.	and the same of th
<ol> <li>Brill 7 7/8" hele to TD 4460". Ran open hole legs. Ran 144 jts to esg pt 4456". Gut w/200 ax Incore Pes. Top of cut by Temp 2 pressure test to 1000 psig for 30 min - CK.</li> <li>Ran PFC leg then perf w/l "E" bullet at each of the fellowing do 4262, 4277, 4283, 4292, 4296, 4312, 4314, 4342, 4351.</li> <li>Acidise all perfs w/l500 gal RDA. Swab well, establish flow and acid water.</li> </ol>	Survey 3670 . WOC 24 hre.
4. Potential test for 456 BQFD on 22/64 cheke. TP 260 psig. GQR 7	50:1.
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNED BOOK TITLE District Engineer	DATE 12-13-65
	, (3 <b>h</b> -, 1)

CONDITIONS OF APPROVAL, IF ANY: