

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator Gene Milford dba Milford Pipe & Supply		8. Farm or Lease Name Coleman	
3. Address of Operator Box 427 Tatum, NM 88267		9. Well No. 1	
4. Location of Well UNIT LETTER M , 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 24 TOWNSHIP 7-S RANGE 33-E NMPM.		10. Field and Pool, or Wildcat Chaveroo San Andres	
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Roosevelt	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug & Abandon as follows;

3-11-74

Set Cast Iron Bridge Plug @ Appx. 4100' & dump cement to 4065'
Set 100' Cement plug @ 4 1/2" Csg. Stub
Set 100' Cement plug @ top of Salt Section if exposed
Set 100' Cement plug in and out of surface csg.
Set 10 Sacks cement plug @ surface & install dry hole marker

Note; All plugs will be set with, and hole circulated with mud.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Gene Milford TITLE owner DATE 3-11-74

APPROVED BY Joe D. [Signature] TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: