

Form 3160-5
(November 1983)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

3160-5
SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. LC-062529A	
2. NAME OF OPERATOR PLAINS PETROLEUM OPERATING COMPANY		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 415 W. WALL, SUITE 1000 MIDLAND, TX 79701		7. UNIT AGREEMENT NAME Todd Lower S A Unit. Sec.25	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit Letter P, 660' FSL & 660' FEL		8. FARM OR LEASE NAME	
14. PERMIT NO.		9. WELL NO. 16	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4151 GL		10. FIELD AND POOL, OR WILDCAT Todd Lower S A Assoc	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec.25, T7S, R35E	
		12. COUNTY OR PARISH Roosevelt	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PCLL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

In response to your letter dated Jan. 20, 1994, PPOC plans to plug and abandon this well and requests approval of the following plugging program.

1. Set plug across perfs 4230'-73' (~~10-6x~~). 150' cmt. plug from PSTD to 4150'. Tag plug.
2. Cut and recover approximately 3500' of 4-1/2" casing
3. Set 10-6x plug at TOC 130' cmt. plug centered on stub. Tag plug
- * → 4. Set 10-6x plug at surface csg shoe @ 272'. 76-xx, 100' cmt. plug 722'-222'. Tag plug
5. Set surface plug with marker minimum 50' cmt. plug

API No. 30-041-10406

* additional cmt. plug, 2035'-1915'.



18. I hereby certify that the foregoing is true and correct

SIGNED

Bruce Husband

TITLE

Administrative Assistant

DATE

Jan. 28, 1994

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

approved as modified.

FEB 1 1994

*See Instructions on Reverse Side