

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOBBS OFFICE O. C. C.
NEW MEXICO OIL CONSERVATION COMMISSION
DEC 16 12 41 PM '65

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-3935

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Sunray Oil Company	8. Farm or Lease Name N. M. State "AZ"
3. Address of Operator P. O. Box 1416, Roswell, New Mexico	9. Well No. 14
4. Location of Well UNIT LETTER H , 1980 FEET FROM THE H LINE AND 660 FEET FROM THE E LINE, SECTION 34 TOWNSHIP 7S RANGE 33E NMPM.	10. Field and Pool, or Wildcat Chaveros San Andres
15. Elevation (Show whether DF, RT, GR, etc.) Furnish Later	12. County Roosevelt

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER Commence drlg operations <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Spud well 12-11-65. Drld 11" hole to 365', Ran 11 jts, 8 5/8", 2 1/2", J-55 csg to csg pt 361'.
- Cut w/250 sx neat cut w/2% CaCl. Circ 20 sx to surface. WOC 18 hrs. Pressure test to 1000 psig for 30 min - OK.
- Now drlg ahead.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John Hastings John Hastings TITLE Production Engineer DATE 12-15-65

APPROVED BY _____ TITLE _____ DATE DEC 17 1965

CONDITIONS OF APPROVAL, IF ANY: