

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FEB 3 3 43 PM '66

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
Fee	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- DRY - PLUG AND ABANDON		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
TEXACO Inc.		A. B. Hogan
3. Address of Operator		9. Well No.
P. O. Box 728 - Hobbs, New Mexico		1
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>D</u> , <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM		Wildcat
THE <u>West</u> LINE, SECTION <u>3</u> TOWNSHIP <u>8-S</u> RANGE <u>34-E</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
4302' (DF)		Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Total Depth - 4650'
7-5/8" OD casing cemented @ 360'
4-1/2" OD casing cemented @ 4650'

We have plugged and agandoned subject well as follows:

1. Spot 20 sx plug from 4350' to 4615', perforations 4436' to 4549'.
2. Cut off and pull 4-1/2" OD casing, cut off spot 2613'.
3. Spot 50 sx plug 2015' to 2700'. (Top of Salt @ 2150')
4. Spot 25 sx plug 300' to 400'.
5. Spot 10 sx surface plug inside 7-5/8" OD surface casing. Clean location for inspection by NMOCC, install 4" steel marker extending 4' above ground level. Plug and abandon complete February 1, 1966.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dan Gillett TITLE Assistant District Superintendent DATE February 3, 1966

APPROVED BY Leslie A. Clements TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: