

COPIES RECEIVED	
TRIBUTION	
FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Cene Milford dda Milford Pipe & Supply		8. Farm or Lease Name Coleman
3. Address of Operator Box 427 Tatum, NM 88267		9. Well No. 2
4. Location of Well UNIT LETTER 1 , 1980 FEET FROM THE South LINE AND 600 FEET FROM THE West LINE, SECTION 24 TOWNSHIP 7-S RANGE 33-E NMPM.		10. Field and Pool, or Wildcat Chaveroo San Andres
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Roosevelt

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well Plugged & Abandoned as follows:

3-16-74

Set CIBP @ 3998'
Dumped 35' Cement from 3998' to 3963'
Shot 4 1/2" Csg. @ 1402', 1301' and 1202'
Recovered Csg. from 1202'
Spotted 40 sks. cement plug @ 1202' to 1017'
Spotted 40 sk. cement plug @ 50' to 380'
Spotted 50 sd cement plug @ 10' to surface
Installed dry hole marker

Note; All plugs set with, and hole circulated w/ brine salt gelled mud

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>Gene Milford</i></u>	TITLE <u>owner</u>	DATE <u>4-17-74</u>
APPROVED BY <u><i>John W. Ramsey</i></u>	TITLE <u></u>	DATE <u>JUL</u>
CONDITIONS OF APPROVAL, IF ANY:		