

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator	5. State Oil & Gas Lease No.
3. Address of Operator <i>Gene Milford dba Milford Pipe Supply</i>	7. Unit Agreement Name
4. Location of Well <i>Box 427 Tatum, NM 88267</i>	8. Farm or Lease Name <i>Coleman "B"</i>
UNIT LETTER _____, _____ FEET FROM THE _____ LINE AND _____ FEET FROM _____	9. Well No. <i>1</i>
THE _____ LINE, SECTION _____ TOWNSHIP _____ RANGE _____ NMPM.	10. Field and Pool, or Wildcat <i>Chaveroo San Andres</i>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <i>Roosevelt</i>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to Plug & Abandon as follows:

3-11-74

Set Cast Iron Bridge Plug @ Appx. 4100' & dump Cement to 4065'
Set 100' Cement plug @ 4" Csg. stub.
Set 100' Cement plug @ top of Salt Section if exposed
Set 100' Cement plug in and out of surface csg.
Set 10 Sacks cement plug at surface & install dry hole marker

Note: All plugs will be set with and hole circulated with, mud.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Gene Milford TITLE owner DATE 3-11-74

Orig. Signed by
Joe D. Roney
Dist. 1, Supv.

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: