

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLI
(Other instructions
verse side)DE-
re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0108997-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Farrell Federal

9. WELL NO.

13

10. FIELD AND POOL, OR WILDCAT

Chaveroo San Andres

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 28, T-7-S, R-33-E

12. COUNTY OR PARISH

Roosevelt

13. STATE
NMSUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Coquina Oil Corporation

3. ADDRESS OF OPERATOR

P. O. Drawer 2960, Midland, TX 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FNL & 660' FWL, Sec 28

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4432

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

Temporary Abandon

☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Coquina Oil Corporation purchased this well from Mr. Weldon Guest on November 11, 1975. At the time of the purchase the well was uneconomical to produce, therefore, we have carried it as shut-in. The reasons Coquina has not plugged this well are that: currently, we are in the process of studying the possibility of a secondary recovery program, secondly, we may possibly return it to producing status, depending upon the price of oil in the future.

This approved

abandonment expiration

DEC 1 1976

18. I hereby certify that the foregoing is true and correct

SIGNED C. Alan BumpTITLE Engineering Asst.DATE 12-30-75

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

ACCEPTED FOR RECORD
JAN 13 1976
U. S. GEOLOGICAL SURVEY
DALLAS, NEW MEXICO

*See Instructions on Reverse Side