Form 9-331 (May 1963) DEPAR	UNI D STATES TMENT OF THE INTER GEOLOGICAL SURVEY	SUBMIT IN TRIPLA E* (Other instructions on re- verse side)	Form appro-Budget Bure 5. LEASE DESIGNATION NM-0108997-B	eau No. 42-R1424
(Do not use this form for pro- Use "APPLI	OTICES AND REPORTS posals to drill or to deepen or plug CATION FOR PERMIT—" for such	ON WELLS g back to a different reservoir.	6. IF INDIAN, ALLOTTI	EE OR TRIBE NAME
OIL X GAS WELL OTHER	7. UNIT AGREEMENT NAME			
2. NAME OF OPERATOR Coquina Oil Corporati	on		8. FARM OR LEASE NAME	
3. ADDRESS OF OPERATOR	OII_		Farrell Federal	
			9. WELL NO.	
P. O. Drawer 2960, Midland, TX 79701 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.			12	
See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT			
At surface	Chaveroo San Andres			
			11. SEC., T., R., M., OR SURVEY OR AREA	BLK, AND
1980' FNL & 1980	SURVET OR AREA	A		
			Sec 28 T.7	C D 22 E
14. PERMIT NO.	15. ELEVATIONS (Show whether I	DF, RT, GR, etc.)	12. COUNTY OR PARISE	13. STATE
	44321		Roosevelt	NM
16. Check A	Appropriate Box To Indicate	Nature of Notice, Report, or O		
NOTICE OF INTI		SUBSEQUENT REPORT OF:		
TEST WATER SHUT-OFF			7	<u></u>
	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING	WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING C	ASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONME	NT*
REPAIR WELL CHANGE PLANS (Other)				[]
(Other) Temporary	Completion or Recomple	s of multiple completion on Well pletion Report and Log form.)		
 DESCRIBE PROPOSED OR COMPLETED OF proposed work. If well is direct nent to this work.) * 	ERATIONS (Clearly state all pertine ionally drilled, give subsurface local	ent details, and give pertinent dates, ations and measured and true vertical	including estimated dat I depths for all marker	e of starting any s and zones perti-

Coquina Oil Corporation purchased this well from Mr. Weldon Guest on November 11, 1975. At the time of the purchase the well was uneconomical to produce, therefore, we have carried it as shut-in. The reasons Coquina has not plugged this well are that: currently, we are in the process of studing the possibility of a secondary recovery program, secondly, we may possibly return it to producing status, depending upon the price of oil in the future.

This approval of temperary abandonment explicis DEC 1 1276

8. I hereby certify that the foregoing is true and correct		
SIGNED C Atan Bump	TITLE	Engineering Asst
(This space for Federal or State office use)		ACCEPTED FOR THE
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	JAN 1 3 1970 (AF PARE
*Se	e Instruction	U. S. GECLOGICAL SURVEY U. S. GECLOGICAL SURVEY MEXICO US ON Reverse Side