

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator <u>Gene Milford dba Milford Pipe & Supply</u>		8. Farm or Lease Name <u>Bradley</u>
3. Address of Operator <u>Box 427 Tatum, N.M. 88267</u>		9. Well No. <u>2</u>
4. Location of Well UNIT LETTER <u>0</u> , <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>24</u> TOWNSHIP <u>7-S</u> RANGE <u>33-S</u> NMPM.		10. Field and Pool, or Wildcat <u>Chaveroo San Andres</u>
15. Elevation (Show whether DF, RT, GR, etc.)		12. County <u>Roosevelt</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug & abandon as follows;

311-
3-11-74

Set Cast Iron Bridge Plug @ Appx. 4100' & Dump Cement to 4065'
Set 100' Cement plug @ 4 1/2" Csg. stub
Set 100' Cement plug @ top of Salt Section if exposed
Set 100' Cement plug in and out of surface csg.
Set 10 sacks cement plug @ surface & install dry hole marker

Note: All plugs will be set with and hole circulated with, mud.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Gene Milford TITLE Owner DATE 3-11-74

APPROVED BY Joe D. Ramsey TITLE Dist. I, Supv. DATE _____
CONDITIONS OF APPROVAL, IF ANY: