

NO. OF COPIES RECEIVED

DISTRIBUTION

NATAFE

FILE

U.S.G.S.

LAND OFFICE

OPERATOR

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease

State ☐Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator SUN OIL COMPANY		8. Farm or Lease Name James McFarland "A"	
3. Address of Operator P. O. Box 1861, Midland, Texas 79701		9. Well No. 4	
4. Location of Well UNIT LETTER I, 1979.5 FEET FROM THE South LINE AND 660 FEET FROM East THE LINE, SECTION 20 TOWNSHIP 8S RANGE 33E NMPM.		10. Field and Pool, or Wildcat Chaveroo San Andres	
11. Elevation (Show whether DF, RT, GR, etc.) GR. 4422		12. County Roosevelt	

6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐PLUG AND ABANDON ☒REMEDIAL WORK ☐ALTERING CASING ☐TEMPORARILY ABANDON ☐CHANGE PLANS ☐COMMENCE DRILLING OPNS. ☐PLUG AND ABANDONMENT ☐PULL OR ALTER CASING ☐OTHER ☐CASING TEST AND CEMENT JOB ☐OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU
2. Pull rods, pump and tbq.
3. Run tbq OE, spot 40 sx cmt. plug across perfs 4310 to 4095.
4. WOC 4 hrs. Tag plug, circulate hole w/9.5# mud laden fluid. POH.
5. Locate free point, shoot and pull 4½" csg. Anticipate 3000' recovery.
6. Run tbq. Spot 30 sx cmt. plug 50' in and out of 4½" csg. stub.
7. Spot 50 sx cmt. plug 2350 to 2250 across base of salt.
8. Spot 50 sx cmt. plug 1950 to 1850 across top of salt.
9. Spot 50 sx cmt. plug 425 to 325 across 8-5/8" csg. seat.
10. Apot 10 sx cmt. plug at surface, weld cap on 8-5/8", install permanent marker.

Use Class "H" cmt, mud laden fluid between plugs.

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED.

Expires 4/1/77

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE

Proration Analyst

DATE

9/27/76

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: