NO. OF COPIES RECEIVED		•	Form C-103
DISTRIBUTION	HOBBS OFFICE O. C. C		Supersedes Old
SANTA FE			G-102 and G-103
FILE		MAY I OS PM'S	C
U.S.G.S.			5a. Indicate Type of Lease
LAND OFFICE			State X Fee.
OPERATOR			5. State Oil & Gas Lease No. K 3935
SUNDR (DO NOT USE THIS FORM FOR PRO USE **APPLICAT	Y NOTICES AND REPORTS ON POSALS TO DRILL OR TO DEEPEN OR PLUG BAON FOR PERMIT - 101) FOR SUCH	WELLS ICK TO A DIFFERENT RESERVOIR.	
l. OIL	OTHER•		7. Unit Agreement Name
Name of Operator			8. Farm or Lease Name
Sunray DX 011 Company	Sunray DX 011 Company		
. Address of Operator			New Mexico State "AZ" 9. Well No.
P. O. Box 1416, Roswel	l, New Mexico		16
Location of Well			10. Field and Pool, or Wildcat
UNIT LETTER,	990 FEET FROM THE South	LINE AND 990 FEET FROM	Chaveroo San Andres
THE West LINE, SECTION	N 34 TOWNSHIP 78	RANGE 33E NMPM	
······			
15. Elevation (Show whether DF, RT, GR, etc.)		12. County	
	Appropriate Box To Indicate Na		Roosevelt \\\\\\\
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER Completion	ALTERING CASING PLUG AND ABANDONMENT Report
OTHER	U		
1. Drill 350', 12 1/4' Circ ent. WOC 18 1 2. Drill 7 7/8" hole 1 Incor Poz 2% Gel. 3. Ran PFC Log 4437 to	hole. Run 8 5/8" casin hrs. Test 1000# for 30 m to 4470' TD. Run open ho WOC 24 hrs. Test to 100 b 4000'. Perf 1 hole at 3. Acidize w/500 gal BDA	ng. Cut casing w/250 stain. Ple logs. Run 4 1/2" 9 00 psig for 30 min. 4302, 4308, 4318, 4323	x reg cmt. 2% CaCl5# csg. Cmt w/200 sx
5. Swab all load oil.			
6. Potential 169 Bbl	oil, 23 Bbl water 24 hrs	, GOR 600.	