

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

HOBBS OFFICE O. C. C.

APR 8 10 45 AM '66

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No. K-3935	
7. Unit Agreement Name	
8. Farm or Lease Name New Mexico State "AZ"	
9. Well No. 16	
10. Field and Pool, or Wildcat Chaveroo San Andres	
12. County Roosevelt	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Sunray DX Oil Company
3. Address of Operator P. O. Box 1416, Roswell, New Mexico	4. Location of Well UNIT LETTER M 990 FEET FROM THE South LINE AND 990 FEET FROM THE West LINE, SECTION 34 TOWNSHIP 78 RANGE 33E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) Furnish Later	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER Commence drilling operation <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Spud well 4-2-66. Drld 11" hole to 345'. Ran 11 jts, 8 5/8", 24#, J-55 csg to csg. pt 344'.
- Cmt'd with 200 sxs reg cmt, 2% CaCl. Circ approx 50 sxs to pit. WOC 18 hrs. Pressure test to 1000# for 30 min. - OK.
- Now drlg ahead.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John Hastings TITLE Production Engineer DATE 4-7-66

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: