N. M. CIL COMS. COMMISSION -

P. O. BOX 1930 UNITED STATES HOBBS, NEW WEXING OR 186040 E. Form approved. Budget Bureau No. 42-R1424. Form 9-331 (May 1963) DEPARTMENT OF THE INTERIOR verse side) 5. LEASE DESIGNATION AND SERIAL NO. NM-042253 GEOLOGICAL SURVEY 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.) 7. UNIT AGREEMENT NAME 1. WE'L X WELL OTHER 8. FARM OR LEASE NAME 2. NAME OF OPERATOR Fed. Z Dalport Oil Corporation 9. WELL NO. ADDRESS OF OPERATOR 3471 Inter First One, Dallas, TX 75202 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\* See also space 17 below.)
At surface 10. FIELD AND POOL, OR WILDCAT <u>Chaveroo</u> 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 660' FNL & 660 FEL LeHer "A" 26-T975 -R33E 12. COUNTY OR PARISH 13. STATE 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14 PERMIT NO. Roosevelt NM Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data 16. SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: REPAIRING WELL WATER SHUT-OFF PULL OR ALTER CASING TEST WATER SHUT-OFF ALTERING CASING FRACTURE TREATMENT MULTIPLE COMPLETE FRACTURE TREAT ABANDONMENT\* SHOOTING OR ACIDIZING X ABANDON\* SHOOT OR ACIDIZE (Other) . CHANGE PLANS (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\* T.D. 4400', PBTD 4367', Perfs. 4119' - 4259' DATA: 8 5/8" Csg. set @ 363 Circulated.  $4\frac{1}{2}$ " Csg. set @ 4397 w/300 SX Load 4½" Csg. with Mød, set C.I.B.P. @ 4000' w/35' cmt. plug. PROCEDURE: Run 2 3/8" tbg. to 3150'; set cement plug @ 3150' to 3000! tag plug. Shoot 4½" Csg. @ 400'; set cmt. plug, 450' to 300' tag plug. Set 10SX plug @ surface and install dry hole marker. 18. I hereby certify that the foregoing is true and correct TITLE . SIGNED (This space for Federal or State office use) TITLE APPROVED BY

\*See Instructions on Reverse Side

CONDITIONS OF APPROVAL, IF ANY:

DEC 9 1987

BUREAU OF LAND MANAGEMENT ROSWELL RESOURCE AREA ARCENER DECT 1 1981