

COPIES RECEIVED		
DISTRIBUTION		
FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-1276	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	
2. Name of Operator Braden-Deam, Inc.	
3. Address of Operator 200 E. First, Wichita, Kansas 67202	
4. Location of Well UNIT LETTER L , 1980 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 25 TOWNSHIP 7S RANGE 33E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) 4338 RDB	

7. Unit Agreement Name
8. Farm or Lease Name State DB
9. Well No. 4
10. Field and Pool, or Wildcat Chaveroo (San Andres)
12. County Roosevelt

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set cement plug over perforations 4208-4263' 100' Plug. MIN.

2. Fill hole with mud laden fluid. - 2500 ~~per~~ 100 bbl's brine H₂O (9.5# H₂O)

3. Shoot off and pull 4 1/2' casing at approximately 2400'. - 100' plug IN & out stub of 4 1/2" CSg. + 100' plug TOP OF SALT

4. Plug hole as directed by Conservation Commission representative.

NOTIFY Commission 24 hrs. Prior to setting btm. plug

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE Vice-President	DATE 11/18/74
APPROVED BY <u>[Signature]</u> Orig. Signed By Los Clemente State Oil & Gas	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		