

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>K-4840</b>
7. Unit Agreement Name -----
8. Farm or Lease Name <b>Capitan</b>
9. Well No. <b>1</b>
10. Field and Pool, or Wildcat <b>Wildcat</b>
12. County <b>Roosevelt</b>

<b>SUNDY NOTICES AND REPORTS ON WELLS</b> <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator <b>Morris R. Antweil</b>
3. Address of Operator <b>Box 2010, Hobbs, New Mexico</b>	4. Location of Well UNIT LETTER <b>L</b> , <b>1980</b> FEET FROM THE <b>South</b> LINE AND <b>660</b> FEET FROM THE <b>West</b> LINE, SECTION <b>8</b> TOWNSHIP <b>7S</b> RANGE <b>34 E</b> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) <b>KB 4336'</b>	12. County <b>Roosevelt</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 4290', Spotted 25 sx cement plug across perfs 4030'--4172'.  
Cut 4-1/2" csg. @ 3200' and pulled casing. Spotted 25 sx cement  
plug across 4-1/2" casing stub @ 3200'. Spotted 25 sx cement  
plug across top of salt @ 1650'. Spotted 25 sx cement plug  
across shoe of 8-5/8" casing @ 403'. Spotted 10 sx. cement plug  
in top of 8-5/8" casing and erected 4' X 4" marker.  
Plugged and Abandoned 9-30-66.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>R M Williams</u>	TITLE <u>Agent</u>	DATE <u>10-18-66</u>
APPROVED BY <u>John W. Runyan</u>	TITLE _____	DATE <u>10</u>
CONDITIONS OF APPROVAL, IF ANY:		