

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
		5. State Oil & Gas Lease No.
1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Gene Milford dba Milford Pipe & Supply		8. Farm or Lease Name Bradley
3. Address of Operator Box 427 Tatum, NM 88267		9. Well No. 4
4. Location of Well UNIT LETTER P , 660 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 24 TOWNSHIP 7-S RANGE 33-E NMPM.		10. Field and Pool, or Wildcat Chaveroo- San Andres
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Roosevelt

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug & abandon as follows:
3-11-74

Set Cast Iron Bridge plug @ Appx 4100' & dumb cement to 4065'
Set 100' Cement plug @ 4 1/2' Csg. Stub
Set 100' Cement plug @ top of Salt Section if Exposed
Set 100' Cement plug in and out of surface csg.
Set 10 Sacks Cement plug AT Surface & install dry hole marker.

Note: All plugs will be set with and hole circulated with, mud.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNED <u>Gene Milford</u>	TITLE <u>Owner</u>	DATE <u>3-11-74</u>	
APPROVED BY <u>Joe D. Ramey</u>		DATE _____	
CONDITIONS OF APPROVAL, IF ANY:		TITLE <u>Dist. I, Supv.</u>	