NO. OF COPIES RECEIVED DISTRIBUTION	
DISTRIBUTION	F 0 1-4
HODDE OFFICE O C C	Form C-103 Supersedes Old
SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE	THECHAE 1-1-02
U.S.G.S. APR 20-1 26 PN '66	5a. Indicate Type of Lease
LAND OFFICE	State 🗶 Fee.
OPERATOR	5. State Oil & Gas Lease No.
	K-9735
SUNDRY NOTICES AND REPORTS ON WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO BRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. 1.	
OIL GAS	7. Unit Agreement Name
WELL OTHER.	22
Sunray DX 011 Company 77267	8. Farm or Lease Name
3. Address of Operator	New Mexico Gaste "CC"
P. O. Box 1416, Roswell, New Mexico	9. Well No.
4. Location of Well	1
UNIT LETTER G 1840 FEET FROM THE North LINE AND FE	10. Field and Pool, or Wildcat
UNIT LETTER G 1840 NOTEN 1840 FEET FROM THE LINE AND FEET FROM THE	EET FROM TONG SEN Andres
East 32 7S 35E	
THE East LINE, SECTION TOWNSHIP RANGE	_ NMPM. ()
15. Elevation (Show whether DF, RT, GR, etc.)	
	12. County
Furnish Later	Roosevelt
Check Appropriate Box To Indicate Nature of Notice, Report	or Other Data
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB	ALTERING CASING PLUG AND ABANDONMENT ATTEMPT OPERATIONS X
TEMPORARILY ABANDON COMMENCE DRILLING OPNS. PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT Adrilling operations X Accluding estimated date of starting any proposed /8", 24#, J-55 to csg pt 364'
Commence Drilling opns. Casing test and cement job other To Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, in work) SEE RULE 1103. 1. Spud well 4-13-66. Drld 11" hole to 365'. Ran 11 jts, 8 5/ 2. Cat w/200 sxs reg 2% CaCl, Circ approx 50 sxs to pit, WOC 18 1000# for 30 min - OK.	PLUG AND ABANDONMENT Adrilling operations X Accluding estimated date of starting any proposed /8", 24#, J-55 to csg pt 364'