

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division  
P.O. Box 1980  
Hobbs, NM 88241

FOMM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well  
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

PERMIAN RESOURCES, INC DBA PERMIAN PARTNERS, INC.

3. Address and Telephone No.

P.O. BOX 590 MIDLAND, TEXAS 79702

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Location: 660' FS&WL of Sec 29-7S-33E

5. Lease Designation and Serial No.  
NM0554778

6. If Indian, Allottee or Tribe Name

7. If Unit or C.A. Agreement Designation

8. Well Name and No.

Lauck Federal #14

9. API Well No.

30-041-10561

10. Field and Pool, or Exploratory Area

Chaveroo San Andres

11. County or Parish, State

Roosevelt, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☒ Other Plug & Abandon  
☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Operator will notify BLM well as follows:

of plugging operations and plug and abandon

- Pump a 20 sx cement plug down tubing to cover perforations at 4200'. Let set and pressure test.
- Back off tubing 2600'  $\pm$ . Set 20 sx plug & tag. Shoot 4 1/2" casing at 390'  $\pm$ . Set 100' cement plug in 4 1/2".
- 100' cement plug in 8 5/8" casing & tag.
- 10 sx plug at surface. Clean location & set P&A marker.

14. I hereby certify that the foregoing is true and correct

Signed

Title

Vice President

Date

9-9-98

(This space for Federal or State office use)

Any

Conclusions or approvals, if any.

ORIG. SGD. GARY GOUPLEY

Title

PETROLEUM ENGINEER

Date

SEP 22 1998

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instruction on Reverse Side