

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

1

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work). *

Zone has been depleted w/ no workover or recompletion possibilities.
Propose to P & A as follows.

- 1- Cut and pull 4 1/2" casing from free point (TCMT 3240')
- 2- Load hole w/ mud
- 3- Set 25 lb cement plug PBD 475' - 3900' (Perfs 4042-4245)
- 4- " 35 " " " In + out of 4 1/2" Stub
- 5- " 35 " " " Across B Salt @ 2960'.
depending on where casing is cut. plug 4+5 may be combined
to form plug if top of casing & B Salt is within 300' of
each other. Cement volume may be increased to insure a
100' min plug.
- 6- Set 35 lb plug across T Salt @ 1820' (1890-1750')
- 7- " 35 " In + out of 8 7/8" CSA 358' (310-410)
- 8- " 10 " @ surface + set pt A marker.
- 9- Make final cleanup + level location.

TD - 4300
PB - 4254
4 1/2" CSA 4300
8 5/8" CSA 3582

18. I hereby certify that the foregoing is true and correct.

ADMINISTRATIVE ASSISTANT

DATE _____

9-18-75

(This space for Federal or State office use)

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

DATE _____

APPROVED
AS AMENDED
NOV 6 1975
U.S. B. BROK
COIN

ARTHUR
DISTRICT ENG

044-USGS-1d
1- DIV
1- SUSP
1- 1214

*See Instructions on Reverse Side

SE. SICKLE
ARTHUR R. BROWN
ENGINEER