

U.S. CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ For ☐
5. State Oil & Gas Lease No.
OC-1395

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator TEXACO Inc	8. Farm or Lease Name New Mexico CT State
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240	9. Well No. 4
4. Location of Well UNIT LETTER C 660 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 35 TOWNSHIP 7-S RANGE 35-E N.M.P.M.	10. Field and Pool, or Wildcat Todd-Upper San Andres Gas
15. Elevation (Show whether DF, RT, GR, etc.) 4189' (DF)	12. County Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RIG UP. INSTALL BOP. PULL TUBING.
2. SET CEMENT RETAINER @ 4075'. SQUEEZE PERFORATIONS 4125' - 4196' W/100 SX CLASS H NEAT CEMENT. CAP W/5 SX CEMENT FROM 4075' - 4040'.
3. CUT 4 1/2" CASING AT FREEPOINT AND PULL SAME.
4. SPOT 25 SX CEMENT PLUG FROM 50' BELOW STUB TO 50' ABOVE CASING STUB.
5. SPOT 25 SX CEMENT PLUG FROM 2120' - 2020'.
6. SPOT 36 SX CEMENT PLUG FROM 397' - 297'.
7. SPOT 21 SX CEMENT PLUG FROM 100' - SURFACE.
8. INSTALL DRY HOLE MARKER AND CLEAN LOCATION. PLUG AND ABANDON WELL.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE ASST DIST MGR DATE 10-4-83

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON TITLE DISTRICT SUPERVISOR DATE OCT 19 1983
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
COT 4 1983
O.C.D.
HOBBS OFFICE