

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

M. Oil Cont. Division
25 N. French Dr.
obs, NM 88240

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1999

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well ☒ Oil Well ☐ Gas Well ☐ Other	5. Lease Designation and Serial No. NM 050477A
2. Name of Operator Permian Resources Incorporated	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. P.O. Box 590, Midland, TX 79702-0590	7. If Unit or C.A. Agreement Designation
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 660' FNL & 1980' FWL of 1660 Sec. 27, T-7S, 33E	8. Well Name and No. Card Federal #2
	9. API Well No. 30-041-10622
	10. Field and Pool, or Exploratory Area Chaveroo (San Andres)
	11. County or Parish, State Roosevelt, NM

CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION	
☒ Notice of Intent	☒ Abandonment	☐ Change of Plans
☐ Subsequent Report	☐ Recompletion	☐ New Construction
☐ Final Abandonment Notice	☐ Plugging Back	☐ Non-Routine Fracturing
	☐ Casing Repair	☐ Water Shut-Off
	☐ Altering Casing	☐ Conversion in Injection
	☐ Other _____	☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Well uneconomical to produce. Proposed plugging procedure:

1. Pump LCM pill to TD/perfs and follow with 25 sx cement, tag; circulate w/gelled brine.
2. Cut casing at free point, set 100' plug; tag; circulate gel.
3. Set 100' cement plug at base of 8-5/8" shoe.
4. Set 10 sx cement plug at surface; install P&A marker.

APPROVED
PETER W. CHESTER
MAY 16 2000
BUREAU OF LAND MANAGEMENT
ROOSEVELT RESOURCE AREA

I hereby certify that the foregoing is true and correct

Signed Sherry Conrad Title Production Clerk Date 5-11-00

(This space for Federal or State office use)

Approved by _____ Title _____ Date _____

Conditions of approval, if any: _____

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

S GWW

RECEIVED

MAY 12 2000

BLM
ROSWELL, NM

WELL NAME: CARD FE #2 LEASE NO. NM 050477A
LOCATION 660N, 1980W, 27-7S-33E COUNTY: ROOSEVELT
API# 30-041-10622

12 7/4" HOLE

8 5/8" CASING

SET AT 360 FT
WITH 260 SACKS
TOC CIRC FT

7 7/8" HOLE

5 1/2" CASING

SET AT 4610 FT
WITH 400 SACKS
TOC 1563 FT.

TD

4610

④ 10' SX PLUG AT SURFACE;
INSTALL PTA MARKER.

③ PUMP 100' PLUG ACROSS
BASE OF 8 5/8" CASING; CIRCULATE
GELLED BRINE.

② CUT CASING AT FREEPOINT;
PUMP 100' PLUG; TAG; CIRCULATE
GELLED BRINE. (± 1400')

① PUMP LCM PILL TO PERFS/TD;
PUMP 25 SX; TAG; CIRCULATE
WITH GELLED MUD.

PERFS 4148-4297

RECEIVED

MAY 12 2000

BLM
ROSWELL, NM