DISTRIBUTION SANTA FE FILE	<u>.</u>	Supersedes Old
FILE	NEW MEXICO OIL CONSERVATION COMMISSION : .	C-102 and C-103 Effective 1-1-65
	NEW MEXICO OIL CONSERVATION COMMISSION	***************************************
U.S.G.S.	$M_{ m c}$	5a. Indicate Type of Lease
LAND OFFICE		State Fee
OPERATOR		5. State Oil & Gas Lease No.
		K-2672
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		
• USE APPLICATION FOR	PERMIT - (FURM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
OIL GAS WELL OTH	HER•	None
. Name of Operator		8. Farm or Lease Name
Southern Petroleum Exple	oration. Inc.	State K
. Address of Operator		9. Well No.
Box 1434, Roswell, New 1	Mexico	6
Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER	FEET FROM THE NOTTH LINE AND 1980 FEET FROM	Chaveroo
Mank	7.	
THE WOST LINE, SECTION	36 TOWNSHIP 7-S RANGE 33-E NMPM.	
	15, Elevation (Show whether DF, RT, GR, etc.)	12. County
	4324 GR	
		Roosevelt (\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
	priate Box To Indicate Nature of Notice, Report or Otl	
NOTICE OF INTENT	TION TO: SUBSEQUENT	REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
EMPORARILY ABANDON ULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
DEL OR ALTER CASING		
	OTHER	
OTHER		
OTHER		
7. Describe Proposed or Completed Operation work) SEE RULE 1 103.	s (Clearly state all pertinent details, and give pertinent dates, including	
7. Describe Proposed or Completed Operation work) see RULE 1903. Ran 4462 of 4-1/2" Lone: Pos with 2% gel. and 8#	star, 10.50#, J-55 new casing, cemented salt per sack. Used guide shoe, float volume. 10-7-66. Waited 18 hours for cemen	with 350 sacks Incor alve and six centra- t to set. Tested
7. Describe Proposed or Completed Operation work) SEE RULE 1103. Ran 4462 of 4-1/2" Lones Pos with 2% gel. and 8# lisers. Plug down 5:30 geasing with 1000# for 30 3400.	star, 10.50#, J-55 new casing, cemented salt per sack. Used guide shoe, float volume. 10-7-66. Waited 18 hours for cemen	with 350 sacks Incor alve and six centra- t to set. Tested ad top of cement at
7. Describe Proposed or Completed Operation work) SEE RULE 1103. Ran 4462 of 4-1/2" Lones Pos with 2% gel. and 8# lisers. Plug down 5:30 geasing with 1000# for 30 3400.	star, 10.50#. J-55 new casing, cemented salt per sack. Used guide shoe, float vol.m. 10-7-66. Waited 18 hours for cementain. Held O.K. Temperature survey four	with 350 sacks Incor alve and six centra- t to set. Tested ad top of cement at
7. Describe Proposed or Completed Operation work) SEE RULE 1103. Ran 4462 of 4-1/2" Lones Pos with 2% gel. and 8# lisers. Plug down 5:30 geasing with 1000# for 30 3400.	star, 10.50#. J-55 new casing, cemented salt per sack. Used guide shoe, float vol.m. 10-7-66. Waited 18 hours for cementain. Held O.K. Temperature survey four	with 350 sacks Incor alve and six centra- t to set. Tested ad top of cement at