

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

L CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
OG-930	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator American Trading and Production Corporation		8. Farm or Lease Name New Mexico State "20"
3. Address of Operator 110 W. Louisiana, Suite 300; Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER <u>L</u> , <u>660</u> FEET FROM THE <u>West</u> LINE AND <u>1980</u> FEET FROM THE <u>South</u> LINE, SECTION <u>20</u> TOWNSHIP <u>7S</u> RANGE <u>34E</u> NMPM.		10. Field and Pool, or Wildcat Chaveroo (San Andres)
15. Elevation (Show whether DF, RT, GR, etc.) 4326 KB		12. County Roosevelt

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-18-87 Set CIBP @ 4090' w/35' cmt cap.  
11-19-87 Cir. hole w/+ 10#/gal mud.  
11-21-87 Spot 10 sx cmt plug from 1464-1321'. Shot & pulled 4½" csg. @ 469'.  
Spot 55 sx plug from 519-353'.  
11-22-87 Tagged plug @ 353'. Spot 10 sx plug @ surface & erect dry-hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Engineer DATE 12-8-87

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE MAR 28 1989  
CONDITIONS OF APPROVAL, IF ANY: