DISTRIBUTION SANTA FE	4 · · · · · · · · · · · · · · · · · · ·	
		Form C-103
	A Supplementary of All Supplementary of the	Supersedes Old C-102 and C-103
FILE	HEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
U.S.G.S.	Aug 24 11 44 AH '66	
LAND OFFICE	The state of the s	5a. Indicate Type of Lease State
OPERATOR		5. State Oil & Gas Lease No.
	· · · · · · · · · · · · · · · · · · ·	K-1370
SUNDI (DO NOT USE THIS FORM FOR PR USE "APPLICA"	RY NOTICES AND REPORTS ON WELLS OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. TION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL GAS	TOTAL TOTALS.	7. Unit Agreement Name
2. Name of Operator	OTHER-	***
		8. Farm or Lease Name
3. Address of Operator		Nobbs "W"
P. A. Bon 730 a	Waling Warm Manuface	9. Well No.
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER	330 FEET FROM THE HOPEN LINE AND 980 FEET FR	Character Sen Andreas
-	LINE AND FEET FR	
THELINE, SECTION	ON TOWNSHIP TOL RANGE SO-	
mmmmmm		
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
16. Check	Appendices P. T. I. I.	Roccevelt //////////
NOTICE OF IN	Appropriate Box To Indicate Nature of Notice, Report or O	ther Data
	SUBSEQUEN	NT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERNIA ALAMA
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JCB	THE REPUBLICATION OF THE PROPERTY CONTRACTOR OF
07115	OTHER	
отнек	erations (Clearly state all pertinent details, and give pertinent dates, including	
17. Describe Proposed or Completed Opwork) SEE RULE 1703. Reached total 4-1/2*** 10.56 of cement by trapozature or ourlose. Total		s. (4420°) of new I with 350 seeks .H. August 19, 1966.
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Resched total 4-1/2 0 10.56 of count by the Tampeschuse or auxiliary. Not the total described of the	erations (Clearly state all pertinent details, and give pertinent dates, including the state of 4430 on August 13, 1966. Set 140 jt. 82 38 J-55 R-2 REM casing at 4430 cannot be pump and plug process. Plug down at 3:00 A rever indicated cannot outside 4-1/2" casing at 4401 casing up to 4000 for 30 mills not drill out cannot plug. P.B.T.B. 4401.	s. (4420°) of new I with 350 seeks .H. August 19, 1966.
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Reached total 4-1/2 0 10.56 of count by the Temposeture or surface. Westerd CE. 3.	erations (Clearly state all pertinent details, and give pertinent dates, including depth of 4430° on August 18, 1966. Set 140 jt. 82 86 J-55 R-2 EERS casing at 4430°. Commente he pump and plug process. Plug down at 5:00 A svey indicated cament outside 4-1/2°00 casing 24 hours, presented casing up to 400f for 30 mill act cament plug. P.B.T.B. 4401°.	t with 350 sacks N. August 19, 1966. It 3389 from the limites and easing