

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

WATER CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
OG-930	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator American Trading and Production Corporation		8. Farm or Lease Name New Mexico State "20"
3. Address of Operator 110 W. Louisiana, Suite 300; Midland, Texas 79701		9. Well No. 2
4. Location of Well UNIT LETTER <u>M</u> <u>660</u> FEET FROM THE <u>West</u> LINE AND <u>660</u> FEET FROM THE <u>South</u> LINE, SECTION <u>20</u> TOWNSHIP <u>7S</u> RANGE <u>34E</u> NMPM.		10. Field and Pool, or WHdcat Chaveroo (San Andres)
15. Elevation (Show whether DF, RT, GR, etc.) 4325' KB		12. County Roosevelt

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

11-19-87 Set CIBP @ 4140' w/35' cmt cap. Cir hole w/+ 10#/gal mud.
11-20-87 Shot & pulled 4½" csg @ 979'. Spot 25 sx plug from 1030-868'. W.O.C. 3 hrs.
Tag plug @ 868'. Spot 45 sx plug from 475-362'.
11-21-87 Tag plug @ 362'. Spot 10 sx plug @ surface & erect dry-hole marker

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Engineer DATE 12-8-87

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE MAR 28 1988

CONDITIONS OF APPROVAL, IF ANY: