

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
<b>K-1370</b>

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>SKELLY OIL COMPANY</b>	8. Farm or Lease Name <b>Hobbs "W"</b>
3. Address of Operator <b>Box 730; Hobbs, New Mexico 88240</b>	9. Well No. <b>5</b>
4. Location of Well UNIT LETTER <b>J</b> <b>2310</b> FEET FROM THE <b>South</b> LINE AND <b>1980</b> FEET FROM THE <b>East</b> LINE, SECTION <b>30</b> TOWNSHIP <b>7S</b> RANGE <b>34E</b> NMPM.	10. Field and Pool, or Wildcat <b>Chaveros San Andres</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4321' DF</b>	12. County <b>ROOSEVELT</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <b>Perforate, acidize and frac.</b> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**Pull rods and tubing. Perforate 4-1/2" OD casing 4239-4323'.**

**Run tubing, packer and retrievable bridge plug.**

**Treat casing perforations with acid and ball sealers.**


**Pull tubing, packer and bridge plug.**

**Treat down casing through perforations with lease crude and sand.**

**Run tubing, pump and rods and return to production status.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **(Signed) V. E. Fletcher** TITLE **District Superintendent** DATE **April 11, 1968**

APPROVED BY  TITLE **SUPERVISOR** DATE **APR 11 1968**

CONDITIONS OF APPROVAL, IF ANY:

**MLF:er**