

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

IL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. OG-930
7. Unit Agreement Name
8. Farm or Lease Name New Mexico State "20"
9. Well No. 3
10. Field and Pool, or WHdcat Chaveroo (San Andres)
12. County Roosevelt

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator American Trading and Production Corporation
3. Address of Operator 110 W. Louisiana, Suite 300; Midland, Texas 79701
4. Location of Well UNIT LETTER <u>K</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>20</u> TOWNSHIP <u>7S</u> RANGE <u>34E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4312' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-19-87 Set CIBP @ 4150' w/35' cmt cap
11-22-87 Cir. hole w/+ 10#/gal mud. Shot csg @ 2000'. Unable to pull free.
Spot 40 sx plug from 1488-981'.
11-23-87 Tag plug @ 981'. Shot & pulled 4 1/2" csg @ 958'. Spot 15 sx plug from 981-899'.
W.O.C. 3 hrs. Tag plug @ 899'. Spot 55 sx plug from 450' to 349'.
11-24-87 Tag plug @ 349'. Spot 10 sx plug @ surface & erect dry-hole marker

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John P. [Signature] TITLE Engineer DATE 12-8-87
APPROVED BY Jack [Signature] TITLE OIL & GAS INSPECTOR DATE MAR 28 1989
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
DEC 9 1987
OCD
HOBBS OFFICE