NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	UBBS Of Color Color Effective report
FILE		
U.S.G.S.		N 2 5a. Adamste Marchase
LAND OFFICE		State Fee.
OPERATOR	1	5. State Oil & Gas Lease No.
SUNDR (DC NOT USE THIS FORM FOR PRO USE "APPLICAT	RY NOTICES AND REPORTS ON WELLS OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. TION FOR PERMIT " (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL GAS UNCLL	OTHER.	7. Unit Agreement Name
2. Name of Operator	· · · · ·	8. Farm or Lease Name
Morris R. Ant	tweil	Sample
3. Address of Operator		9. Well No.
P. O. Box 201	10, Hobbs, New Mexico	1
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER G, 19	980 FEET FROM THE NOTTH LINE AND 1980 FEET	Wildcat
	<b>A7</b>	
THE LINE, SECTION	10N TOWNSHIP 78 RANGE 34E	MPM. AIIIIIIIIIIIIIIIIIIIII
		м. ж. А//////////////////////////////////
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	15. Elevation (Show whether DF, RT, GR, etc.) <b>KB4281</b>	12. County Roosevelt
	KB4281	Roosevelt
	<b>KB4281</b> Appropriate Box To Indicate Nature of Notice, Report or	Roosevelt
	<b>KB4281</b> Appropriate Box To Indicate Nature of Notice, Report or	Roosevelt Other Data
	<b>KB4281</b> Appropriate Box To Indicate Nature of Notice, Report or	Roosevelt Other Data
	KB4281   Appropriate Box To Indicate Nature of Notice, Report or   NTENTION TO:	Roosevelt Other Data ENT REPORT OF:
NOTICE OF IN	KB4281   Appropriate Box To Indicate Nature of Notice, Report or NTENTION TO:   SUBSEQU   Plug and abandon X   Remedial work   CHANGE PLANS	Roosevelt Other Data ENT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT
NOTICE OF IN	KB4281   Appropriate Box To Indicate Nature of Notice, Report or NTENTION TO:   PLUG AND ABANDON   PLUG AND ABANDON   REMEDIAL WORK   COMMENCE DRILLING OPNS.	Roosevelt Other Data ENT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK	KB4281   Appropriate Box To Indicate Nature of Notice, Report or NTENTION TO:   SUBSEQU   Plug and abandon X   Remedial work   CHANGE PLANS	Roosevelt Other Data ENT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT

TD 4690'. Cemented 4-1/2", 10.5#/ft. New Csg. @ 4689' w/325 sxs., W.O.C. 24 hrs. Tested csg. to 1,000 psi. for 30 mins. No decline in pressure. Top cement 3500'. Perforated 4495, 4502, 10, 18, 25, 29, 40 & 44. Treated w/1500 gals. MCA and retreat w/4,000 gals. 15% HCL. Swabbed dry w/slight show gas & oil. Ran and set bridge plug at 4462'. Perf. 2 shots per ft. 4419, 24, & 29. Treated w/1500 gals. & retreat w/1750 gals. MCA. Swabbed dry w/slight show gas, no show oil. Plan to P & A. 1/25/67, as fellows: (Verbal approval by J. D. Ramey) 25 sx. cement plug on Btm. & across perforations. Cut and pull approx. 3450' of 4-1/2" csg. 25 sx. cement plug across 4-1/2" csg. 25 sx. cement plug across top salt (approx. 2100'.) 25 sx. cement plug across top salt (approx. 2100'.) 25 sx. cement plug in base of 8-5/8" surface at 410'. 10 sx. cement plug at surface xx w/marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNED	DATE	1-25-67
APPROVED BY JOL Of Charge TITLE LIPCE VISCIA LASIR	DATE	JAN 27 1967
CONDITIONS OF APPROVAL, IF ANY		