

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOBBS OFFICE O. C. C.  
NEW MEXICO OIL CONSERVATION COMMISSION

FEB 14 10 10 AM '67

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name <b>Davis "A"</b>
9. Well No. <b>#1</b>
10. Field and Pool, or Well <b>UNDESIGNATED</b>
12. County <b>Roosevelt</b>

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Test Well</b>
2. Name of Operator <b>Cities Service Oil Company</b>
3. Address of Operator <b>P. O. Box 69 - Hobbs, New Mexico 88240</b>
4. Location of Well UNIT LETTER <b>M</b> <b>660</b> FEET FROM THE <b>South</b> LINE AND <b>660</b> FEET FROM THE <b>West</b> LINE, SECTION <b>17</b> TOWNSHIP <b>7S</b> RANGE <b>34E</b> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) <b>4315 Est. G.L.</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled to a T.D. of 4315. Set 4295' of 4½" O.D., 9.5#, 8R, J-55 at 4305.29'.  
Cemented with 200 sax Class A cement w/12½# sack gilsonite & 4% gel. Followed  
with 200 sax incor neat. Plug down at 12:10 P.M. 2-11-67. Top of cement at  
3005'. WOC 24 hrs. Test to 1000 psi - no drop in pressure. Release rig.  
Prepare to perforate. Moving in pulling unit.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. D. L. TITLE **District Clerk** DATE **February 13, 1967**  
APPROVED BY [Signature] TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: