Submit 3 Copies to Appropriate District Offices

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240  DISTRICT II P.O. Drawer DD, Artesia, NM 88210  DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			WELL API NO. 30-041-20034  5. Indicate Type of Lease  STATE X FEE  6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name Todd Lwr SA Unit See. 18
1. Type of Well: OIL WELL X GAS WELL	OTHER		
2. Name of Operator Saga Petroleum LLC			8. Well No. 15
3. Address of Operator 415 W Wall, Suite 1900, Midland	I, TX 79701		9. Pool name or Wildcat Todd Lower San Andres Assoc
4. Well Location Unit Letter O :660	_ Feet From The S	Line and _1980	Feet From The _E Line
Section 19	Township 7S	Range 36E N	IMPM ROOSEVELT County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)			
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON  PULL OR ALTER CASING CASING CASING TEST AND CEMENT JOB  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  Set CIBP @ 4200', dump 35' cmt on top (perfs 4235'-4280') Tag  100' plug @ 2035'-1935'  Cut & pull 5-1/2" csg, estimate 1000'  Spot 100' plug @ 8-1/2" stub, Tag  Spot 100' plug @ 8-5/8" shoe (50 in & 50 out) Btm of shoe @ 331', Tag  50' surface plug, install dry hole marker			
I hereby certify that the information above is true a signature	and T	TLE Production Analyst	DATE 09/15/2000  TELEPHONE NO. (915)684-4293
(This space for State Use)			1-
APPROVED BY	ТТ	TLE	DATE