

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. 12641	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator MONUMENT ENERGY CORPORATION	8. Farm or Lease Name HUMBLE TUCKER
3. Address of Operator P.O. BOX 1476 LOVINGTON, NEW MEXICO 88260	9. Well No. 1
4. Location of Well UNIT LETTER <u>N</u> <u>660'</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>WCST</u> LINE, SECTION <u>25</u> TOWNSHIP <u>7-S</u> RANGE <u>32-E</u> NMPM.	10. Field and Pool, or Wildcat CHAUVEROO SAN ANDRES
15. Elevation (Show whether DF, RT, GR, etc.) 4433.5 GL	12. County ROOSEVELT

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>TESTING UPPER SAN ANDRES</u> <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1708.

COMMENCE WORK ON 1-16-76. PULLED RODS & TUBING AND PERFORATED SECTION 4015 TO 4122 WITH 17 SHOTS. SET BRIDGE PLUG AT 4138 AND PACKER AT 3978. SWAB TUBING DRY. PUMPED 1000 GALLONS MCA ACID. FORMATION BROKE DOWN AT 3500# AND PUMPED AT 2.75 BPM AT 2200#. OPENED WELL UP IN 1 HOUR. FLOWED 16 BARRELS. LOAD WATER AND 3 BARRELS ACID WATER. STARTED SWABBING AND SWABBED DRY. SHUT IN 20 HOURS. OPEN WELL AND FOUND 2200' FLUID IN HOLE. SWAB DRY IN 1 HOUR. NO SHOW OF OIL OR GAS. PULLED BRIDGE PLUG AND PACKER AND PUT ON PRODUCTION FROM LOWER ZONE.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. H. Duly TITLE PRODUCTION FOREMAN DATE 4-29-80

Orig. Signed by  
Jerry Sexton

APPROVED BY [Signature] TITLE [Signature] DATE MAY 7 1980

CONDITIONS OF APPROVAL (If any)