NO. OF COPIES RECEIVE	ED]					Form C-103		
DISTRIBUTION							Supersedes O C-102 and C-1		
SANTA FE] и	EW MEXICO OIL	CONS	ERVATION COMMISSION		Effective 1-1-		
FILE									_
U.S.G.S.						ſ	5a. Indicate Type	of Lease	_
LAND OFFICE							State X		ee
OPERATOR						ſ	5. State Oil & Ga		•
							SG & FC #0	GS-1	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. use "application for permit -" (form C-101) for such proposals.)									
OIL X	GAS	OTHER-	<u></u>		_		7. Unit Agreemen	it Nam o	
2. Name of Operator							8. Farm or Lease	Name	
Monument I	Energy Co	rporation					HSG		
Address of Operator							9. Well No.		
Box 1476,	Lovington	n, New Me	xico 88260				1		
. Location of Well		· · · · · ·					10. Field and Po	ol, or Wildee	rt
UNIT LETTER	P	660 FE	ET FROM THE SO	uth	LINE AND 660	FEET PROM	Chaveroo	and the second s	
							MIMM	MMM	////
East East	LINE. SECTI	ON26	TOWNSHIP	7 5	5		HHHHH	//////	())
								ΠΠΠ	ĹΠ
15. Elevation (Show whether DF, RT, GR, etc.)							12. County		////
			4461.1 GR				Roosevelt		\overline{III}
N	Check OTICE OF II			ate N	lature of Notice, Repo SUBS		er Data REPORT OF:		
PERFORM REMEDIAL WOR	. []		PLUG AND ABAND		REMEDIAL WORK		ALTER	ING CASING	
TEMPORARILY ABANDON					COMMENCE DRILLING OPNS.	Fi		AND ABANDONI	MENT
PULL OR ALTER CASING	77						PLUGA		
			CHANGE PLANS				PLUG A		
			CHANGE PLANS		CASING TEST AND CEMENT JO	•	PLUGA		
OTHER			CHANGE PLANS		CASING TEST AND CEMENT JO	s			l
OTHER					CASING TEST AND CEMENT JO				[
OTHER 17. Describe Proposed of work) SEE RULE 1		perations (Clec			CASING TEST AND CEMENT JO				[
<i>work)</i> see rule 1	ſŌĴ.		arly state all pertin		CASING TEST AND CEMENT JO	, including e	estimated date of		
work) see rule'i Pull rods & t	ros. tubing and	d remove	urly state all pertin all pumping	equi	CASING TEST AND CEMENT JOU OTHER ails, and give pertinent dates pment and plug we	, including e	estimated date of		
work) SEE RULE 1 Pull rods & 1 . Set CI BP @ 3	ros. tubing and 3500' and	d remove top with	urly state all pertin all pumping	equi	CASING TEST AND CEMENT JOU OTHER ails, and give pertinent dates pment and plug we	, including e	estimated date of		
work) see RULE1 Pull rods & t . Set CI BP @ 3 35 sacks ceme	ros. tubing and 3500' and ent at stu	d remove top with ub.	urly state all pertin all pumping 5 sacks ce	equi	CASING TEST AND CEMENT JOU OTHER ails, and give pertinent dates pment and plug we	, including e	estimated date of		
work) see RULE1 Pull rods & t Set CI BP @ 3 35 sacks ceme 35 sacks @ to	ros. tubing and 3500' and ent at stu op of sal	d remove top with ub. t1780-1	urly state all pertin all pumping 5 sacks ce	equi	CASING TEST AND CEMENT JOU OTHER ails, and give pertinent dates pment and plug we	, including e	estimated date of		
work) see RULE1 Pull rods & t . Set CI BP @ 3 35 sacks ceme	ros. tubing and 3500' and ent at str op of sal ottom of s	d remove top with ub. t1780-1 surface.	urly state all pertin all pumping 5 sacks ce 880.	equi	CASING TEST AND CEMENT JOU OTHER ails, and give pertinent dates pment and plug we	, including e	estimated date of		
work) SEE RULE 1 Pull rods & t Set CI BP @ 3 35 sacks ceme 35 sacks @ to 35 sacks @ to	ros. tubing and 3500' and ent at str op of sal- ottom of s urface wit	d remove top with ub. t1780-1 surface. th marker	urly state all pertin all pumping 5 sacks ce 880.	equi	CASING TEST AND CEMENT JOU OTHER ails, and give pertinent dates pment and plug we	, including e	estimated date of		[
work) SEE RULE 1 Pull rods & t Set CI BP @ 3 35 sacks ceme 35 sacks @ to 35 sacks @ bo 10 sacks @ su	ros. tubing and 3500' and ent at str op of sal- ottom of s urface wit	d remove top with ub. t1780-1 surface. th marker	urly state all pertin all pumping 5 sacks ce 880.	equi	CASING TEST AND CEMENT JOU OTHER ails, and give pertinent dates pment and plug we	, including e	estimated date of		[
work) SEE RULE 1 Pull rods & t Set CI BP @ 3 35 sacks ceme 35 sacks @ to 35 sacks @ bo 10 sacks @ su	ros. tubing and 3500' and ent at str op of sal- ottom of s urface wit	d remove top with ub. t1780-1 surface. th marker	urly state all pertin all pumping 5 sacks ce 880.	equi	CASING TEST AND CEMENT JOU OTHER ails, and give pertinent dates pment and plug we	, including e	estimated date of		[
work) SEE RULE 1 Pull rods & t Set CI BP @ 3 35 sacks ceme 35 sacks @ to 35 sacks @ bo 10 sacks @ su	ros. tubing and 3500' and ent at str op of sal- ottom of s urface wit	d remove top with ub. t1780-1 surface. th marker	urly state all pertin all pumping 5 sacks ce 880.	equi	CASING TEST AND CEMENT JOU oTHER	, including o	estimated date of 0110ws:	starting any	[
work) SEE RULE 1 Pull rods & t Set CI BP @ 3 35 sacks ceme 35 sacks @ to 35 sacks @ bo 10 sacks @ su	ros. tubing and 3500' and ent at str op of sal- ottom of s urface wit	d remove top with ub. t1780-1 surface. th marker	urly state all pertin all pumping 5 sacks ce 880.	equi	CASING TEST AND CEMENT JOU OTHER ails, and give pertinent dates, pment and plug we THE COMMISS	, including o	estimated date of ollows:	starting any	[
work) SEE RULE 1 Pull rods & t Set CI BP @ 3 35 sacks ceme 35 sacks @ to 35 sacks @ bo 10 sacks @ su	ros. tubing and 3500' and ent at str op of sal- ottom of s urface wit	d remove top with ub. t1780-1 surface. th marker	urly state all pertin all pumping 5 sacks ce 880.	equi	CASING TEST AND CEMENT JOU OTHER ails, and give pertinent dates, pment and plug we THE COMMISS HOURS PRIOT	, including of 11 as f 1071 M.J	estimated date of ollows: ST BE MOTIFIE E BECHNING	starting any	[
work) SEE RULE 1 Pull rods & t Set CI BP @ 3 35 sacks ceme 35 sacks @ to 35 sacks @ bo 10 sacks @ su	ros. tubing and 3500' and ent at str op of sal- ottom of s urface wit	d remove top with ub. t1780-1 surface. th marker	urly state all pertin all pumping 5 sacks ce 880.	equi	CASING TEST AND CEMENT JOU other ails, and give pertinent dates pment and plug we THE COMMISS HOURS PRIOF PLUGGING OF	, including of 11 as f 11 as f	estimated date of ollows: ST BE MOTIFIE E BECHNING	starting any	[
work) SEE RULE 1 Pull rods & t Set CI BP @ 3 35 sacks ceme 35 sacks @ to 35 sacks @ bo 10 sacks @ su	ros. tubing and 3500' and ent at str op of sal- ottom of s urface wit	d remove top with ub. t1780-1 surface. th marker	urly state all pertin all pumping 5 sacks ce 880.	equi	CASING TEST AND CEMENT JOU OTHER ails, and give pertinent dates, pment and plug we THE COMMISS HOURS PRIOT	, including of 11 as f 11 as f	estimated date of ollows: ST BE MOTIFIE E BECHNING	starting any	[
work) SEE RULE 1 Pull rods & t Set CI BP @ 3 35 sacks ceme 35 sacks @ to 35 sacks @ bo 10 sacks @ su	ros. tubing and 3500' and ent at str op of sal- ottom of s urface wit	d remove top with ub. t1780-1 surface. th marker	urly state all pertin all pumping 5 sacks ce 880.	equi	CASING TEST AND CEMENT JOU other ails, and give pertinent dates pment and plug we THE COMMISS HOURS PRIOF PLUGGING OF	, including of 11 as f 11 as f	estimated date of ollows: ST BE MOTIFIE E BECHNING	starting any	[
work) SEE RULE 1 Pull rods & t Set CI BP @ 3 35 sacks ceme 35 sacks @ to 35 sacks @ bo 10 sacks @ su	ros. tubing and 3500' and ent at str op of sal- ottom of s urface wit	d remove top with ub. t1780-1 surface. th marker	urly state all pertin all pumping 5 sacks ce 880.	equi	CASING TEST AND CEMENT JOU other ails, and give pertinent dates pment and plug we THE COMMISS HOURS PRIOF PLUGGING OF	, including of 11 as f 11 as f	estimated date of ollows: ST BE MOTIFIE E BECHNING	starting any	
work) SEE RULE 1 Pull rods & t Set CI BP @ 3 35 sacks ceme 35 sacks @ to 35 sacks @ bo 10 sacks @ su	ros. tubing and 3500' and ent at str op of sal- ottom of s urface wit	d remove top with ub. t1780-1 surface. th marker	urly state all pertin all pumping 5 sacks ce 880.	equi	CASING TEST AND CEMENT JOU other ails, and give pertinent dates pment and plug we THE COMMISS HOURS PRIOF PLUGGING OF	, including of 11 as f 11 as f	estimated date of ollows: ST BE MOTIFIE E BECHNING	starting any	
work) SEE RULE 1 Pull rods & t Set CI BP @ 3 35 sacks ceme 35 sacks @ to 35 sacks @ to 10 sacks @ su 10# mud betwe	ros. tubing and 3500' and ent at str op of sal- ottom of s urface wi- een plugs	d remove top with ub. t1780-1 surface. th marker	uly state all pertin all pumping 5 sacks ce 880.	equi ment.	CASING TEST AND CEMENT JOU oTHER ails, and give pertinent dates, pment and plug we THE COMMISS HOURS PRIOF PLUGGING OF TO BE APPRC	, including of 11 as f 11 as f	estimated date of ollows: ST BE MOTIFIE E BECHNING	starting any	
work) SEE RULE 1 Pull rods & t Set CI BP @ 3 35 sacks ceme 35 sacks @ to 35 sacks @ to 10 sacks @ su 10# mud betwe	ros. tubing and 3500' and ent at str op of sal- ottom of s urface wi- een plugs	d remove top with ub. t1780-1 surface. th marker	uly state all pertin all pumping 5 sacks ce 880.	equi ment.	CASING TEST AND CEMENT JOU other ails, and give pertinent dates pment and plug we THE COMMISS HOURS PRIOF PLUGGING OF	, including of 11 as f 11 as f	estimated date of ollows: ST BE MOTIFIE E BECHNING	starting any	
work) SEE RULE 1 Pull rods & t Set CI BP @ 3 35 sacks ceme 35 sacks @ to 35 sacks @ to 10 sacks @ su 10# mud betwe	ros. tubing and 3500' and ent at str op of sal- ottom of s urface wi- een plugs	d remove top with ub. t1780-1 surface. th marker	uly state all pertin all pumping 5 sacks ce 880.	equi ment.	CASING TEST AND CEMENT JOU OTHER ails, and give pertinent dates, ipment and plug we THE COMMISS HOURS PRION PLUCGING ON TO BE APPRC	, including of 11 as f 11 as f	estimated date of ollows: ST BE MOTIFIE E ESGINNING S FOR THE C	starting any ED 24 OF -103	
work) SEE RULE 1 Pull rods & t Set CI BP @ 3 35 sacks ceme 35 sacks @ to 35 sacks @ to 10 sacks @ su 10# mud betwe	ros. tubing and 3500' and ent at str op of sal- ottom of s urface wi- een plugs	d remove top with ub. t1780-1 surface. th marker	uly state all pertin all pumping 5 sacks ce 880.	equi ment.	CASING TEST AND CEMENT JOU oTHER ails, and give pertinent dates, pment and plug we THE COMMISS HOURS PRIOF PLUGGING OF TO BE APPRC	, including of 11 as f 11 as f	estimated date of ollows: ST BE MOTIFIE E ESGINNING S FOR THE C	starting any	[
work) SEE RULE 1 Pull rods & t Set CI BP @ 3 35 sacks ceme 35 sacks @ to 35 sacks @ to 10 sacks @ su 10# mud betwe	ros. tubing and 3500' and ent at str op of sal- ottom of s urface wi- een plugs	d remove top with ub. t1780-1 surface. th marker	all pumping 5 sacks ce 880.	equi ment.	CASING TEST AND CEMENT JOU OTHER ails, and give pertinent dates, ipment and plug we THE COMMISS HOURS PRION PLUCGING ON TO BE APPRC	, including of 11 as f 11 as f	estimated date of ollows: ST BE MOTIFIE E BEGINNING S FOR THE C	starting any ED 24 OF -103	[
work) SEE RULE 1 Pull rods & t Set CI BP @ 3 35 sacks ceme 35 sacks @ to 35 sacks @ to 10 sacks @ su 10# mud betwe	ros. tubing and 3500' and ent at str op of sal- ottom of s urface wi- een plugs	d remove top with ub. t1780-1 surface. th marker	all pumping 5 sacks ce 880.	equi ment.	CASING TEST AND CEMENT JOU OTHER ails, and give pertinent dates, ipment and plug we THE COMMISS HOURS PRION PLUCGING ON TO BE APPRC	, including of 11 as f 11 as f	estimated date of ollows: ST BE MOTIFIE E BEGINNING S FOR THE C	starting any ED 24 OF -103	