Submit 3 Copies to Appropriate District Offices

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised 1-1-89

DISTRICT I	OIL CONSERVATI	ON DIVISION	
DISTRICT 1 P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION 310 Old Santa Fe Trail, Room 206		WELL API NO.	
DISTRICT II Santa Fe. New Mexico 87503		30-041-20065 5. Indicate Type of Lease	
P.O. Drawer DD, Artesia, NM 88210			
<u>DISTRICT III</u> 1000 Rio Brazos Rd., Aztec, NM 87410			
1000 Rd Drazos Rdi, Filitet, 1111 07410			6. State Oil & Gas Lease No. OG174
SUNDRY NOTICES AND REPORTS ON WELLS			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Todd Lwr SA Unit Sec. 31
1. Type of Well:			
OIL WELL X GAS WELL OTHER			
2. Name of Operator			8. Well No.
Saga Petroleum LLC			10
3. Address of Operator			9. Pool name or Wildcat
415 W Wall, Suite 1900, Midland, TX 79701			Todd Lower San Andres Assoc
4. Well Location Unit Letter J : 2180 Feet From The S Line and 1980 Feet From The E Line			
Section 31	Township 7S R	ange 36E 1	NMPM ROOSEVELT County
	10. Elevation (Show whe	ther DF, RKB, RT, GR, etc.)	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING O			OPNS. L. PLUG AND ABANDON L.
PULL OR ALTER CASING CASING TEST AND CER		MENT JOB	
OTHER:		OTHER:	
	Classic state all northern	et details, and aive partinent de	nter including estimated date of starting any proposed
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.			
Set CIBP @ 4200', dump 35' cmt on top (perfs 4280'-4318') Tag 100' plug @ 2035'-1935' Cut & pull 5-1/2" csg, estimate 1000'			
Spot 100' plug @ 5-1/2" stub, Ta	g		
Spot 100' plug @ 8-5/8" shoe (50 in & 50 out) Btm of shoe @ 331', Tag			
50' surface plug, install dry hole marker			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Brown Squ	oband TI	TLE Production Analys	t DATE _09/15/2000
,			TELEPHONE NO (015)694_4202
TYPE OR PRINT NAME Bonnie Husband TELEPHONE NO. (915)684-4293			
(This space for State Use)		PACT NO.	
		OPACIO LOS RECE	73.4