

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on
reverse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR AMOCO PRODUCTION COMPANY	8. FARM OR LEASE NAME PETERSON A Federal
3. ADDRESS OF OPERATOR BOX 68, HOBBS, N. M. 88240	9. WELL NO. 2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT TODD-LOWER SAN ANDRES
14. PERMIT NO. 1980' FSL x 660' FWL Sec. 29 (Unit L Sec. 29 NW 1/4 SW 1/4)	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 29-7-36-NM PM
15. ELEVATIONS (Show whether of, RT, GR, etc.) 4143' R.D.B.	12. COUNTY OR PARISH ROOSEVELT
	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well is uneconomical and no workover possibilities exist.
Propose to P & A as follows:

Spot 25 Sx cement plug from PBD-4278' to cover perfs: 4232-4272

Fire hole w/ mud.

Shoot & pull 4 1/2" casing from Free Point. (Est approx 2400'.)

25 Sx plug; @ 2100' (if pay out below 2100') (in & out shut if out above 2100')

25 Sx plug in & out of 8 7/8" @ 317'.

10 Sx @ surface and erect P & A marker.

Make final cleanup and restore ground to contour.

TD-4298

PBD-4278

PERFS 4232-4272

8 7/8" CSA 317' - Circ

4 1/2" CSA 4298 - 300 Sx.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE AREA SUPERINTENDENT

DATE MAR 8 1971

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

014-NSGS-H
1-ACJR
1-SUSP
1-RRY

APPROVED

MAR 10 1971

ARTHUR R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side