

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-041-20078	
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. OG 174	
7. Lease Name or Unit Agreement Name Todd Lower San Andres Unit Se	
8. Well No. 9	
9. Pool name or Wildcat Todd Lower San Andres Assoc.	
Feet From The East Line Roosevelt County	
NMPM	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		Todd Lower San Andres Unit	
2. Name of Operator PLAINS PETROLEUM OPERATING COMPANY		8. Well No. 9	
3. Address of Operator 415 W. Wall, Suite 2110 Midland, Texas 79701		9. Pool name or Wildcat Todd Lower San Andres Assoc.	
4. Well Location Unit Letter <u>I</u> : <u>2180</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>31</u> Township <u>7S</u> Range <u>36E</u> NMPM Roosevelt County			
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 4126			

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
11.	

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: Convert to WIW ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
 COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
 CASING TEST AND CEMENT JOB ☐
 OTHER: _____ ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pursuant to approval from OCD

Plains plans to convert this well to active injection status for the waterflood development program at the Todd Lower San Andres Unit.

Rig up pulling unit, pick up injection tubing and packer, set packer within 100 feet of uppermost P2 zone perforations, load annulus with inert packer fluid & pressure test to 300 psi and hold for 30 minutes.

Convert TA well to active WIW

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie Buchanan TITLE Engineering Tech DATE June 8, 1990

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

JUN 13 1990

APPROVED BY _____ Geologist TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: