

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
3. Address of Operator	9. Well No.
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER <u>T</u> <u>7</u> <u>1980</u> FEET FROM THE <u>80</u> LINE AND <u>660</u> FEET FROM	<u>Wildcat</u>
THE <u>E</u> LINE, SECTION <u>10</u> TOWNSHIP <u>7</u> RANGE <u>35</u> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Drilled to TD 4385' Ra n & cemented 4 1/2" Csg. at TD. Perforated and tested zones @ 4373'-4341' Dry. Set Bridge plug & tested 4258'- 4200' Dry, set plugs at following depths-

25 sx @ 4260'  
Cut & pulled 3000' of 4 1/2" Csg.  
25sx. @ 3050'  
25 Sx. @ 1200'  
25 Sx. in and out of surface casing  
10 Sx. at surface

Dry hole marker set in 8 5/8" Casing . Location cleared & abandoned

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Geo W. Baker TITLE Vice President DATE 4-10-68

APPROVED BY John W. Runyan TITLE Geologist DATE 4-10-68

CONDITION OF APPROVAL, IF ANY: