

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-4866	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Sun Oil Company - DX Division	8. Farm or Lease Name N. M. "HH" State
3. Address of Operator P. O. Box 1416 - Roswell, New Mexico 88201	9. Well No. 1
4. Location of Well UNIT LETTER L , 1980 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 20 TOWNSHIP 7-S RANGE 36-E NMPM.	10. Field and Pool, or Wildcat Todd Lower San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 4159 D.F.	12. County Roosevelt

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Filled hole with mud.
2. Put 25 sxs plug 4329-4029.
3. Pulled casing at 3450'.
4. Laid 50 sxs plug 3470 to 3300.
5. Laid 25 sx plug 3078-2992.
6. Laid 25 sx plug 2179-2085 to cover top of salt @ 2125'.
7. Laid 25 sx plug 412 to 324.
8. Laid 10 sx plug 301 to 0.
9. Now filling pits and clearing location. Will notify when ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED F. D. Lebo TITLE District Engineer DATE February 24, 1969

APPROVED BY John W. Runyan TITLE DATE
CONDITIONS OF APPROVAL, IF ANY: