

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLY
(Other instruction
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0367781-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Shell Federal 35

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 35, T-7-S, R-32-E

12. COUNTY OR PARISH

Roosevelt

13. STATE
New Mexico

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Southwestern Natural Gas, Inc.

3. ADDRESS OF OPERATOR
900 Bank of the Southwest - Midland, Texas

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980 from North line & 660 from West line

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4483 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

(Other) Plug back & Recomplete

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Pull rods and pump.
2. Unseat tbg. anchor and pull Tbg.
3. Set Cast Iron Bridge Plug on wire line at 8720' & dump 25 sks. Cmt. with bailer.
4. Free Pt. Csg. & cut with chemical cutter at 7050'.
5. Pull 4 1/2" csg.
6. Run Tbg. open-ended to 7150" & spot 70 Sk. plug back to 6900' in 4 1/2" csg. & 7 7/8" hole.
7. Set Cast Iron Bridge Plug at 4695' and dump 2 sks. Cmt. on plug with bailer.
8. Perf. San Andres selectively.
9. Acidize and fracture treat perforations.

Verbal approval granted 7-3-68 by Mr. Brown, U.S.G.S. in Hobbs, New Mexico.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Office Manager

DATE 7-3-68

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
JUL 5 1968
A. R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side