

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

MIN OIL CONS. COMM. JN

Draper DB  
SUBMIT IN TRIPPLICATE  
(Other instructions on re-  
verse side) 88210

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR  
Monument Resources, Inc

3. ADDRESS OF OPERATOR  
Box 1476 Lovington, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface  
1830 FNL - 660 FEL  
Sec. 20 - 8-S-36E

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, RT, GR, etc.)  
KB 4124

5. LEASE DESIGNATION AND SERIAL NO.  
29-002915

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. NAME OR LEASE NAME  
Petroleum Federal

9. WELL NO.  
1

10. FIELD AND POOL, OR WILDCAT  
Marie Devonian

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
20-8-S-36E

12. COUNTY OR PARISH  
Roswell

13. STATE  
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF  
FRACTURE TREAT  
SHOOT OR ACIDIZE  
REPAIR WELL  
(Other)

☐  
☐  
☐  
☐  
☐

PULL OR ALTER CASING  
MULTIPLE COMPLETE  
ABANDON\*  
CHANGE PLANS

☐  
☐  
☒  
☐  
☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF  
FRACTURE TREATMENT  
SHOOTING OR ACIDIZING  
(Other)

☐  
☐  
☐  
☐

REPAIRING WELL  
ALTERING CASING  
ABANDONMENT\*

☐  
☐  
☒  
☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Rigged up to Plug & Abandon - SET Cement Retainer @ 6170'  
And pumped 190 SACKS Cement Through Retainer and spotted  
10 SACKS ON TOP OF Retainer - Circulated Hole with 10<sup>#</sup> Bore  
mud - Ran Temperature survey and Found Cement @ 5940' on  
Outside of 5 1/2 Casing - Cut 5 1/2 Casing @ 5813' - Recovered  
5813' 5 1/2 Casing - went in Hole with 2 3/8 Tubing and spotted 50  
SACK plug @ 5 1/2 pipe stub. Spotted 50 SACK plug From 4913  
To 4800' - Spotted 50 SACK plug From 4270 To 4370 - Pulled  
Tubing to 3750' and stuck tubing inside of 8 5/8 Casing. Backed  
Tubing off @ 3346' - Tagged Bottom @ 3423 - Pumped 60 SACK  
Plug - Pumped 30 SACK plug @ 522' - Pumped 20 SACK plug @ 200'  
Cut well head 6' below surface and ran 10 SACKS between 13 3/8  
and 8 5/8 - Placed 5 SACKS inside 8 5/8 and placed dry Hole  
marker -

NOTE: LEFT 14 JO. UTS 2 3/8 TUBING IN HOLE FROM 3750' to 3346'

I hereby certify that the foregoing is true and correct

SIGNED

C. D. Healy

TITLE

Prod Foreman

DATE

2-29-84

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED  
PETER CHESTER

SEP 30 1986

BUREAU OF LAND MANAGEMENT  
ROSSELL RESOURCE AREA

\*See Instructions on Reverse Side