

Tri-Service Drilling Company

FIRST NATIONAL BANK BLDG. P. O. BOX 1785 TELEPHONE MU 4-6641

MIDLAND, TEXAS 79701

M. W. BRANUM, PRESIDENT

CARL NEITHERCUTT, VICE-PRESIDENT

L. E. BRANUM, SECRETARY-TREASURER

February 11, 1969

J. M. Huber Corporation
19th Floor Wilco Building
Midland, Texas 79701

Subject: Deviation Record - Petrofina-Federal No. 1, 1830' FNL, 660'
FEL, Sec. 20, T-8-S, R-36-E, Roosevelt County, New Mexico.

Deviation Record

440'	-	1	deg.	9,060'	-	1/4	deg.
912'	-	3/4	deg.	9,165'	-	1/4	deg.
1,418'	-	1/2	deg.	9,650'	-	1/2	deg.
1,975'	-	3/4	deg.	9,832'	-	1/2	deg.
2,480'	-	3/4	deg.	10,090'	-	0	deg.
3,080'	-	1/2	deg.	10,293'	-	1/2	deg.
3,540'	-	3/4	deg.	10,406'	-	0	deg.
3,635'	-	3/4	deg.	10,830'	-	3/4	deg.
4,042'	-	1/2	deg.	10,972'	-	3/4	deg.
4,240'	-	1/2	deg.	11,020'	-	1/2	deg.
4,800'	-	1/4	deg.	11,135'	-	1/4	deg.
4,860'	-	3/4	deg.	11,295'	-	2	deg.
5,170'	-	1	deg.	11,403'	-	2-3/4	deg.
5,670'	-	1	deg.	11,485'	-	2-1/4	deg.
5,890'	-	1	deg.	11,540'	-	1-3/4	deg.
6,390'	-	1-1/4	deg.	11,750'	-	1-1/2	deg.
6,428'	-	1-1/4	deg.	11,920'	-	1	deg.
6,900'	-	3/4	deg.	12,005'	-	1	deg.
7,360'	-	3/4	deg.	12,090'	-	1-1/4	deg.
7,880'	-	1-1/2	deg.	12,420'	-	1	deg.
8,120'	-	1	deg.	12,660'	-	3/4	deg.
8,520'	-	1-1/4	deg.	12,745'	-	3/4	deg.
8,715'	-	1/2	deg.	12,967'	-	3/4	deg.

TRI SERVICE DRILLING COMPANY

By

L. E. Branum, Secretary