

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR JACK L. McCLELLAN	8. FARM OR LEASE NAME SUZANNE FEDERAL
3. ADDRESS OF OPERATOR Box 848, ROSWELL, NEW MEXICO 88201	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FS & EL	10. FIELD AND POOL, OR WILDCAT WILDCAT
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SEC. 23-T8S-R37E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4008' G. L.	12. COUNTY OR PARISH ROOSEVELT
	13. STATE NEW MEXICO

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

THIS WELL WAS PLUGGED AND ABANDONED AS FOLLOWS:

JAN. 23, 1969: SET 25 SACK PLUG AT TOTAL DEPTH (9450')
SET 25 SACK PLUG AT TOP OF WOLFCAMP (8910')
SET 25 SACK PLUG AT TOP OF ABO (7630')
SET 25 SACK PLUG AT TOP OF GLORIETA (5500')

DOWELL PERFORMED THE CEMENT WORK.

FEB. 13, 1969: SET 25 SACK PLUG IN AND OUT OF STUB OF INTERMEDIATE CASING (1505')
SET 25 SACK PLUG AT BASE OF SURFACE CASING (331')
SET 10 SACK PLUG AT SURFACE.

HALIBURTON PERFORMED THE CEMENT WORK.

CLEANED LOCATION AND SET DRY HOLE MARKER AT SURFACE.

1500' OF 8-5/8" CASING WAS PULLED FROM THIS WELL.

18. I hereby certify that the foregoing is true and correct

SIGNED Jack L. McClellan TITLE OPERATOR DATE 2/17/69

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

JUL 10 1969

*See Instructions on Reverse Side

J L GORDON
ACTING DISTRICT ENGINEER