

MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. 5082

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Sage Energy Company 3. Address of Operator P. O. Drawer 3068, Midland, Texas 79702 4. Location of Well UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>EAST</u> <u>West</u> LINE AND <u>660</u> FEET FROM THE <u>South</u> LINE, SECTION <u>36</u> TOWNSHIP <u>8S</u> RANGE <u>34E</u> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 4215' GL	7. Unit Agreement Name none 8. Farm or Lease Name Atlantic State 9. Well No. 1 10. Field and Pool, or Wildcat Vada Penn 12. County Roosevelt
--	---

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

February 11, 1985 Set Cast Iron Bridge Plug at 9600', with 35' cement plug. Top of cement at 9565'.
February 12, 1985 Cut 5 1/2" csg at 5000', set 40 sxs plug at 5000', Top cement plug at 4960'. 8 5/8" is set through San Andres, does not need San Andres plug.
February 15, 1985 Shot 8 5/8", 65' from surface, WIH to 915', spot 60 sx plug inside 8 5/8".
February 16, 1985 Set 70 sx. plug at 351'. Set 6 sx. plug at surface with marker.
Well P&A 2-16-85

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Frances Holzgraf TITLE Production Clerk DATE 2-16-85
APPROVED BY Jack Griffie TITLE OIL & GAS INSPECTOR DATE APR 7 1988
CONDITIONS OF APPROVAL, IF ANY: