

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
P.O. BOX 1980
HOBBS, NEW MEXICO 88240

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. NM-044216C
2. NAME OF OPERATOR MURPHY OPERATING CORPORATION		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Drawer 2648, Roswell, NM 88202-2648		7. UNIT AGREEMENT NAME Bluitt San Andres Unit
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit Ltr. B, 554' FNL & 1874' FEL, Sec. 24, T8S, R37E		8. FARM OR LEASE NAME Bluitt San Andres Unit Sec. 24
14. PERMIT NO.		9. WELL NO. 2
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3987' GR		10. FIELD AND POOL, OR WILDCAT Bluitt San Andres Assoc.
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 24, T8S, R37E
		12. COUNTY OR PARISH Roosevelt
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☒	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

RU PU. TOH w/4683.2' (152 jts.) 2-3/8" 4.7# J-55 tubing. New PBTD 4731.88'. TIH w/AD-1 packer. Set at 4562'. Acidize w/2,000 gals. 15% NeFe. Drop 20 ball sealers. Good ball action. Flush w/21 bbls. fresh water. ISIP - well on vacuum. Maximum rate - 4.2 BPM, average rate - 3.6 BPM. Maximum pressure - 1,800 psi, average rate - 0-1,800 psi. TOH w/packer. TIH w/production string. Return well to production.

18. I hereby certify that the foregoing is true and correct

SIGNED Melinda K. Hickman TITLE Production Supervisor DATE 9-26-88

Melinda K. Hickman

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

*See Instructions on Reverse Side

ACCEPTED FOR RECORD DATE PETER W. CHESTER
OCT 19 1988
BUREAU OF LAND MANAGEMENT NEW MEXICO RESOURCE AREA