

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions
reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 058677-R

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Louise Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Undesignated

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 21, T-8-S, R-36-E

12. COUNTY OR PARISH 13. STATE

Roosevelt New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER ☐ Dry Hole

2. NAME OF OPERATOR

Solar Oil Company

3. ADDRESS OF OPERATOR

P.O. Box 5596-Midland, Texas

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

14. PERMIT NO. 1980' F S L & 660 F E L

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4110.6 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

To Plug and Abandon as follows:

9-8-69 Started Job

1. 40 sk cement plug-9100'-8800' in 5-1/2" OD casing 11. Set regulation marker.

2. Shot off 5 1/2" casing @ 7681' & pulled same

3. Load hole with mud

4. Set 25 sk cement plug 7600'-7500'

5. Set 25 sk cement plug 5600'-5500'

6. Set 25 sk cement plug 4200'-4100'

7. Shot off 8-5/8" OD casing 1,003' and pulled same

8. Set 50 sk cement plug 1050'-988'

9. Set 35 sk cement plug 350'-315'

10. Set 10 sk cement plug in top of level

18. I hereby certify that the foregoing is true and correct

SIGNED

A. D. Durham

TITLE Production Clerk

DATE 12-10-69

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

