(May 1963)  UNITED STATES  DEPARTMEN OF THE INTERIO				SUBMIT IN TRIPLICATE* (Other instructions reverse side)				
(Do not use	JNDRY NOT this form for propos Use "APPLICA	CES AND REP	ORTS ON en or plug back t	WELLS o a different reservoir.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
OIL GAS X OTHER				La de	7. UNIT AGREEMENT NAME			
2. NAME OF OPERATOR  JACK L. MCCLELLAN			The state of the s		8. FARM OR LEASE NAME ATLANTIC FEDERAL			
3. Address of open		- Roswell,	NEW MEXA	co 88201	9. WELL NO.			
	L (Report location cl		10. FIELD AND POOL, OR WILDCAT  BLUIT SAN ANDRES ASSO  11. SEC., T., E., M., OR BLK. AND  SURVEY OR AREA					
14. PERMIT NO.		15. ELEVATIONS (Show	whether DF, RT, G	R, etc.)	24-8S-37E NMPM  12. COUNTY OR PARISH 13. STATE  ROOSEVELT N. MEX.			
16.	Check Ap	propriate Box To I	ndicate Natur	e of Notice, Report, or C	<u> </u>			
	NOTICE OF INTEN	UENT REPORT OF:						
TEST WATER SH FRACTURE TREAT SHOOT OR ACIDIS REPAIR WELL (Other)	A C	ULL OR ALTER CASING ULTIPLE COMPLETE BANDON* HANGE PLANS	X	Completion or Recompl	REPAIRING WELL  ALTERING CASING  ABANDONMENT*  of multiple completion on Well etion Report and Log form.)			
THIS WORK PERFOR AND FR	ELL WAS DR ATED IO HO ACED WITH LL. PRODU	ILLED TO A LES 48021-4 15,000 GAL CTION STEAD	TOTAL DE 821.51, GEL BRING	PTH OF 4909' - ACIDIZED WITH 5 E AND 15,000# s	including estimated date of starting any place of the starting and starting any place of the starting and starting any place of the starting and starting any place of the starting any place of the starting and starting any place of the starting and starting any place of the starting any place of the starting and starting and starting and starting any place of the starting and starting any place of the sta			

SE TO PLUG AND ABANDON AS 100' PLUG 4860' - 4760' 100' PLUG IN AND OUT OF RECOVERED 42" csg. 15 sks in top of 8 5/8"

- 1. Place additional 100 foot cement plug at 260 to 360 feet.
- 2. If 45" casing is pulled from below 2100 feet, place additional 100 foot cement plug at 2000-2100 feet.
- 3. Hole to be filled between plugs with 9.5# (minimum) brine-gel mud.

18. I hereby certify that the gooding is true and correct SIGNED	PRODUCTION SUPERINTENDENT			DAT.	DATE APRIL 3, 1972		
(This space for Federal or State office rise)						<del></del>	
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE _	<u> </u>	AP	AMENUTY:		<del></del>	
*Se	e Instruct	tions on Reve	Side AR	PR 4 1912. THUR R. BROWN INSTRICT INCINES	RAS		

PIETVID

K. 1182

OIL CONSPENSACE COLUM. BOBES, N. M.