Submit 3 Copies to Appropriate

State of New Mexico

N.M. OII Cons. Division 1(3 N. French Dr. Form C-103 Energy, Minerals and Natural Resources Departmen Hobbs, NM 88240 Revised 1-1-89

District Office

DISTRICT I P.O. Box 1980, Hobbs, NM 88240 **OIL CONSERVATION DIVISION**

WELLAPI NO.

, , , , , , , , , , , , , , , , , , , ,			40 Pacheco ର nta Fe, NM		05		30 925 -20206			
DISTRICT II P O. Drawer DD, Artesia, NM 882	10	Oa.	12 10, 1111	5.0	- -	İ	sIndicate Type of Lea			
DISTRICT III							State Oil & Gas Leas	STATE	FEE	
1000 Rio Brazos Rd., Aztec, NM 8	37410						NM-1737	7	,	
SUNDRY NOTICES AND REPORTS ON WELLS										
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)							Lease Name or Unit Agreement Name Federal "18"			
Type of Well: OIL Gr WELL W	AS	Ī	THER TA'd C	oil we	1				······································	
:Name of Operator Pure Resources, L.P.							₃Well No. 1			
Address of Operator	NATIONAL TO						₃Pool name or Wildca Bluitt San Andro			
500 W. Texas, Ste. 200,	Midiand, IX	79701					Dialit San Andre	C3 7 G30Clated		
∙Well Location Unit Letter O :	660 Fee	et From The	south		_ Line and	1980	Feet From The	east	Line	
Section	18	Township	88		ange	38E	NMPM	Roosevelt	County	
₁₀Elevatior: (Show whether DF, RKB, RT, GR, etc.)										
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data										
NOTICE OF INTENTION TO SUBS						SEQUENT REPORT OF:				
PERFORM REMEDIAL WORK		PLUG AND A	BANDON		REMEDIAL W	ORK		ALTERING CAS	SING	
TEMPORARILY ABANDON		CHANGE PLA	NS [COMMENCE	DRILLING O	PNS.	PLUG AND AND	ANDONMENT	
PULL OR ALTER CASING					CASING TEST	T AND CEME	ENT JOB			

:Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set retainer @ 4670'; dump 2 sx cernent on retainer.

OTHER: Plugback to shallower zone

Perf Milnesand 4588' - 4625'. Set packer @ 4500'. Acidize; swab. Frac w/ 14,000 gals gel and 20,000 lbs sand at 12 bpm. Flow to recover load. Circulate clean. Set production equipment, place on production for testing.

Work Must Commence Within 45 Days After Approval (08-19-2000).

I hereby certify that the information above is the and complete to the best of my knowledge and belief.	
I hereby certify that the information above is inverand complete to the best of my knowledge and belief. SIGNATURE TITLE Regulatory Analyst	DATE 06-20-00
TYPE OR PRINT NAME Laura Clepper	тецерноме мо. 915/685-7607